

TOP SECRET

ROUTING	
1	9
2	10
3	11
4	12
5	13
6	14
7	15
8	16

IN: 80373

25X1A

OPS 10 ID

TOP SECRET 151211Z CITE [REDACTED] 1259

CITE

25X1A

PRIORITY [REDACTED]

INFO [REDACTED]

25X1A

25X1A

- A. BX6739
- B. FINAL EVALUATION OF INS DATA
- C. INS 010
- D. DATA STARTS LINE 15, TIME 021124 - BIASED
DATA ENDS LINE 1185, TIME 065046 - BIASED

ALL LINES OF ELAPSED TIME, GROUND SPEED, LONGITUDE AND LATITUDE WERE BIASED DURING LAUNCH IN ORDER TO CHECK SUSPECTED INS PROBLEM. TIME WAS NOT AVAILABLE TO RE-INITIALIZE RECORDER AND PAYLOAD. CHANGES AS FOLLOWS:

ELAPSED TIME - SUBTRACT 182 SECONDS

GROUND SPEED - SUBTRACT 659 KNOTS

LONGITUDE - ADD 31 HUNDREDTHS OF DEGREE


LATITUDE - SUBTRACT 2 HUNDREDTHS OF DEGREE

THESE CHANGES ALSO PERTAIN TO PACKAGE DATA CHAMBER.

LINE 21 BAD DUE TO TAPE TRANSPORT TURN ON: SUGGEST DELETION.

TOP SECRET

IN: 80373



1259

T O P S E C R E T

PAGE 2

LINE 523 ELAPSED TIME READS 10270: SUGGEST 10279.

LINE 661 ELAPSED TIME READS 11570: SUGGEST 11579.

T O P S E C R E T TOR: 151240Z DEC 67

T O P S E C R E T